# Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: THOMPSON 15-31H

Field Name: SOUTH MEADOW Well File #: 20186

Date Incident:8/10/2015Time Incident:20:30Facility ID Number:County:WILLIAMSTwp:158Rng:96Sec:31Qtr:

**Location Description:** 

Submitted By: Alex Beach Received By:

Contact Person: Jason Henry

3015 16th Street SW, Suite 20

Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine

Other 1 Barrels

**Description of Other Released Contaminant:** 

**Emulsion** 

Inspected: Written Report Received: 9/21/2015 Clean Up Concluded: 8/24/2015

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

An estimated 15' by 2' area.

Page 1 of 2

# Potential Environmental Impacts:

There is no data to support any potential environmental impacts at this time.

#### Action Taken or Planned:

Arrangements were made for the impacted material to be cleaned up and disposed of.

Wastes Disposal Location: The waste will be taken to an approved waste disposal facility.

Agencies Involved:

## **Updates**

Date: 8/11/2015 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to an unknown cause, impacted soils with an emulsion off the well pad in an area approximately 15' by 2', according to the report. More followup is needed to verify report accuracy, due to missing information within report.

Date: 9/10/2015 Status: Inspection Author: Kangas, Kathleen

Updated Oil Volume:

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

No impact seen on-site.